

SUBJECT: Motor Parts & Price List
All models.

DATE: March 31, 1932

TO ALL OFFICES:

The following furnishes an up-to-date motor parts and price list grouped according to model.

GROUP NO. 1 MOTOR PART NO. K793A CONTINUOUS RUNNING K MODEL

<u>PART NO.</u>	<u>NAME</u>	<u>PRICE EACH</u>
M 103	Screw in toggle switch K797 OS	\$.05
M 104	Oil cup	.30
M 105	End plate for A.C.	3.00
M 106 No. 1	Rotor Assembly	3.00
M 107	Spring for cut-out	.15
M 108	Fibre washer for cut-out clip	.02
M 109	Screw for cut-out clip	.05
M 110	Brass spacer for cut-out clip	.03
M 111	Insulation bushing for M 109	.05
M 112	Clip for automatic cut-out	.15
M 113 No. 1	Stator (Specify cycle and voltage)	12.45
M 114	End shield Rear A.C.	4.00
M 115	Insulating washer for automatic cut-out	.10
M 116	Automatic cut-out	.80
M 117	Terminal stud	.20
M 118	Brass washer for terminal stud	.05
M 119	Thumb nut for terminal stud	.10
M 120	Screw for end shield	.05
M 121	Insulating bushing for cut-out cover	.20
M 122 No. 1	Screw for M 116	.05
M 125	Cap for brush holder	.10
M 126	Brush holder.	.90
M 127 No. 1	Armature complete with commutator and shaft (Specify voltage)	6.00
M 128	End plate for D.C.	3.00
M 129	Brush spring	.05
M 130	Brush	.20
M 131	Brass brush terminal	.15
M 132	Screw for shutter	.10
M 133	Shutter for D.C.	.50
M 134	Rear end shield for D.C.	4.00
M 135	Field for D.C. (Specify voltage)	5.00
M 136	Set screw for brush holder	.05
M 140	Screw for end shield D.C.	.05
M 155	Nut for switch	.05
M 174	Fibre end thrust washers. Thick	.02
M 175	Fibre end thrust washers. Thin	.02
M 178 No. 1	Centrifugal switch assembly complete	1.25
M 188 No. 1	Flange for cut-out clips A.C. motor	.20
M 203 No. 1	Bronze bearing for D.C. front & rear, and rear on A.C.	.90
M 204 No. 1	Bronze bearing for A.C. front	.90
M 207 No. 1	Motor frame	5.00

GROUP NO. 2 PART NO. K7-94 CONTINUOUS RUNNING K MODEL

<u>PART NO.</u>	<u>NAME</u>	<u>PRICE EACH</u>
M 106 No. 2	Rotor assembly	\$3.00
M 107	Spring for cut-out clip	.15
M 108	Fibre washers for cut-out clip	.02
M 109	Screw for cut-out clip	.05
M 110	Brass spacer for cut-out clip	.03
M 111	Insulation bushing for M 109	.05
M 112	Clip for automatic cut-out	.15
M 113 No. 2	Stator (Specify cycle and voltage)	12.45
M 115	Insulating washer for automatic cut-out	.10
M 116	Automatic cut-out	.80
M 120	Screw for end shield	.05
M 122 No. 1	Screw for M 116	.05
M 150	A.C. end shield	5.00
M 151	Cover for wool pack box	.25
M 152	Spring for wool pack cover	.10
M 153	Cable bushing for A.C.	.20
M 155	Nut for switch	.05
M 174	Fibre end thrust washers. Thick	.02
M 175	Fibre end thrust washers. Thin	.02
M 178 No. 1	Centrifugal switch assembly complete	1.25
M 188 No. 1	Flange for cut-out clips A.C. motor	.20
M 205	Bronze bearing for front A.C.	.90
M 206	Bronze bearing for rear A.C.	.90
M 207 No. 2	Motor frame	5.00

GROUP NO. 3 PART NO. K7-94D START AND STOP K MODEL

<u>PART NO.</u>	<u>NAME</u>	<u>PRICE EACH</u>
M 106 No. 3	Rotor assembly	\$3.00
M 113 No. 3	Stator (Specify cycle and voltage)	12.45
M 120	Screw for end shield	.05
M 126	Brush holder	.90
M 127 No. 3	Armature complete with commutator and shaft (Specify voltage)	6.00
M 129	Brush spring	.05
M 130	Brush	.20
M 131	Brass brush terminal	.15
M 133	Shutter for D.C. motor	.50
M 135 No. 3	Field for D.C. motor (Specify voltage)	5.00
M 150	A.C. end shield	5.00
M 151	Cover for wool pack box	.25
M 152	Spring for wool pack cover	.10
M 153	Cable bushing for A.C.	.20
M 155	Nut for switch	.05
M 157	Rear D.C. end shield	5.00
M 158	Front D.C. end shield	5.00
M 159	Cable bushing for D.C.	.20
M 160	Bushings for brush lead wires	.10
M 166	Set screw for armature core	.10
M 170	Fibre brush lead bushing D.C.	.05
M 171	Field coil fibre insulator D.C.	.02

GROUP NO. 3 PART NO. K7-94D START AND STOP K MODEL (Cont'd)

<u>PART NO.</u>	<u>NAME</u>	<u>PRICE EACH</u>
M 174	Fibre end thrust washers. Thick	\$.02
M 175	Fibre end thrust washers. Thin	.02
M 177	Screws for N.S. shutter	.05
M 182	Centrifugal switch assembly complete (Specify cycle)	1.50
M 183	Cut-out lever	.35
M 184	Stud for fastening cam plate	.10
M 185	Springs for cut-out lever	.10
M 186	Cam spring (Specify cycle)	.20
M 187	Cam plate	.25
M 205	Bronze bearing for front A.C.	.90
M 206	Bronze bearing for rear A.C.	.90
M 207 No. 3	Motor frame	5.00
M 208	Screw for cut-out lever	.15

LA MOTOR 27-794, LA POWER UNIT NO. 27-794X1 AND MA POWER UNIT NO. 30-794X2

<u>PART NO.</u>	<u>NAME</u>	<u>PRICE EACH</u>
LM 1	Frame	\$ 3.85
LM 2	L. H. end shield	2.75
LM 4	Frame bolts	.05
LM 5	Nuts for holding L. H. shield to bolts	.05
LM 6	Name plates	.20
LM 7	Name plate screws LA motors	.02
LM 10 No. 1	Field coils for 110 volt motor	2.30
LM 10 No. 2	Field coils for 105 volt motor	2.30
LM 10 No. 3	Field coils for 170 volt motor	2.30
LM 10 No. 4	Field coils for 220 volt motor	2.30
LM 10 No. 5	Field coils for 250 volt motor	2.30
LM 12	Bronze thrust washers	.05
LM 14	Brush holder for armature brushes	.15
LM 15	Spring for armature brushes	.10
LM 16	Armature brushes	.10
LM 17	Cap for armature brushes	.05
LM 18	Brush holder for governor contact plate brush	.20
LM 19	Spring for governor contact plate brush	.05
LM 20	Governor contact plate brush	.20
LM 21	Brush holder set screws	.05
LM 22	Soft rubber bushing for motor leads	.05
LM 23	Bronze armature bearings	.60
LM 24	Contact screw for motor	.65
LM 25	Brush lead connectors	.05
LM 26	Brush holder fibre washers	.05
LM 27	Frame bolt lock washers -	.03
LM 28	Slot head nuts for fastening stator in frame	.05
LM 30	Governor assembly complete	2.70
LM 31	Governor plate assembly	1.35
LM 32	Governor contact disk	1.35
LM 33	Screw for holding plate to disk	.05
LM 34	Set screw for governor 4-48 thread	.05

LA MOTOR 27-794, LA POWER UNIT NO.27-794x1 AND MA POWER UNIT NO.30-794x2

(Continued)

<u>PART NO.</u>	<u>NAME</u>	<u>PRICE EACH</u>
LM 35	Set screw for governor 6-40 thread	\$.05
LM 40 No. 1	Armature for 110 volt motor	4.60
LM 40 No. 2	Armature for 105 volt motor	4.60
LM 40 No. 3	Armature for 170 volt motor	4.60
LM 40 No. 4	Armature for 220 volt motor	4.60
LM 40 No. 5	Armature for 250 volt motor	4.60

* OLD STYLE MA MOTOR NO.30-794 AND G.E. UNIVERSAL MOTOR FOR K MODEL

<u>PART NO.</u>	<u>NAME</u>	<u>PRICE EACH</u>
MM 1	Carbon brush and brush spring	\$.25
MM 2	Screw for fastening Bakelite end shield to frame	.05
MM 3	Brush holder	.20
MM 4	Brush holder cap	.05
MM 5	Rubber bushing for motor leads	.03
MM 6	End shield ring and studs	.10
MM 7	Bakelite end shield	1.50
MM 8	Name plate	.20
MM 10	Hexagon nut to fit clamping stud	.02
MM 11	End shield cap nuts	.05
M 201	Governor contact screw cover for G.E. Universal K model only	.25
M 211	Governor plate assembly for G.E. Universal motor K model only	1.50

*This is not a complete list and will be supplemented at a later date.

J. M. Smith

General Service Manager

FMS:V

Mr. B. P. James,
Toledo, Ohio.

Dear Mr. James:

I have the honor to acknowledge the receipt of your letter of the 10th inst. in relation to the matter of the Toledo, Ohio, and to inform you that the same has been forwarded to the proper authorities for their consideration.

Very respectfully,
J. B. James

Enclosed for you are two copies of the report of the Toledo, Ohio, and to inform you that the same has been forwarded to the proper authorities for their consideration.

I am, Sir, very respectfully,
Your obedient servant,
J. B. James

Very respectfully,
J. B. James

General Services Bureau